


1/29

Attorney Case No: /08-135 USA 000






FIG. 2

3/29




FIG. 3A




FIG. 3B

5/29




FIG. 4A

6/29




FIG. 4B

7/29




FIG. 5

8/29




FIG. 6



9/29




FIG. 7A

10/29




FIG. 7B




FIG. 8

12/29




FIG. 9

13/29




FIG. 10

[illegible]

15/29




FIG. 12A

16/29




FIG. 12B






FIG. 13

18/29




FIG. 14

19/29




FIG. 15

20/29




FIG. 16

21/29





FIG. 17A







FIG. 18

24/29



Fourth Illustrative Embodiment

Cash Register  
+  
Customer Kiosk  
Terminal

FIG. 19



25/29




FIG. 20




FIG. 21

27/29




FIG. 22A




FIG. 22B




FIG. 23